

Sector	QPCode	Job Role Name	NSQF Level	Equipment Name	Minimum number of Equipment required (per batch of 30 trainees)	Unit Type	Is this a mandatory Equipment to be available at the Training Center (Yes/No)	Dimension/Specification/Description of the Equipment/ ANY OTHER REMARK
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Screw Driver	15	sets	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Phase Tester	5	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Combination Pliers	5	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Nose Pliers	5	units	Yes	

Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Spanner Set	5	set	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Adjustable Wrench	5	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Pipe Wrench	5	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Measuring Tape	3	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Hack Saw	3	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Hammer	5	units	Yes	

Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Chisel	5	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Files	3	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Wood Saw	3	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Poker	5	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Center Punch	5	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Crimping Tool	5	units	Yes	

Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Portable Electric Drill Machine	3	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Bench Vise & Line Vise	3	sets	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Soldering Iron	5	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Blow Lamp	5	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Cable Socket Punching Tool	3	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Digital Multimeter	2	units	Yes	

Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Clip On Meter Or Clamp On Tester	4	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Hi-Pot Set	1	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Megger(Analogue)	2	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Earth Tester	2	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Neon(Power) Tester	1	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Transformer Oil Testing Kit	1	unit	No	

Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Discharge Rod	1	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Ladder	1	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Safety Safety Helmet	2	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Safety Rubber Rubber Gloves	2	pair	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Danger Sign Board	1	each	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Safety Belt Or Full Body Harness	1	set	Yes	

Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Safety Sign Board	1	set	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Safety Boot	2	pairs	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Tagging	3	sets	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Rubber Mat	1	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Mask	1	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	RMU	1	unit	No	

Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Oil Circuit Breaker/ Air Circuit Breaker	1	unit	No	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Isolators For Demo Operation	1	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Old Ht Panels	1	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	IDMT Relay Analog	2	units	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Digital Relays(SC, E/F & OC)	1	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Fault Passage Indicator(FPI)	1	units	Yes	

Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Temperature Meter Analog	1	unit	Yes	
Power	PSS/Q3002	Attendant Sub-Station (66/11,33/11 KV)-Power Distribution	3	Temperature Meter Digital	1	unit	Yes	

