

Sector	QPCode	Job Role Name	NSQF Level	Equipment Name	Minimum number of Equipment required (per batch of 30 trainees)	Unit Type	Is this a mandatory Equipment to be available at the Training Center (Yes/No)	Dimension/Specification/Description of the Equipment/ ANY OTHER REMARK
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Cable	50	Metre	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Crimping Tool	5	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Desktop (Processor Above Intel Pentium 3)	5	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Digital Multimeter	5	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Dot Matrix Printer	1	Units	No	

Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	ESD Gloves	5	Pairs	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Ink Jet Printer	1	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Insulation Tape	5	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Lan Tester	3	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Laptop(Processor Above Intel Pentium 3)	3	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Lead Solder	2	Boxes	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Motherboard Diagnoser	1	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Multi-Function Laser Printer	1	Units	Yes	

Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Network Switch	3	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Post Cards	3	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Router	3	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Scanner	1	Units	No	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Screw Driver Set	5	Units	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Soldering Flux	2	Boxes	Yes	
Electronics	ELE/Q4601	Field Technician – Computing & Peripherals	4	Soldering Iron (Temperature Controlled)	5	Units	Yes	